Sanitized Copy Approved for Release 2010/05/25 : CIA-RDP89B00569R000200150074-6

0550Z 24 JAN 53

SECRET

DIRECTOR

25X1

25X1

OSA/TCO (1-2-3-4-5-6-7-8)

PRIORITY

TOR 09252 24 JAN 63

IH 63517

PRITY

2909

. THIS IS TECH EVAL MISSION 3215.

- P BAND HOISY FROM AC ON. L BAND AND Y BAND QUIET. S BAND MOISY. NOISE REGULAR, PROBABLY MOTOR ABOARD PLANE. REQUEST IN FUTURE IF TAPE IS OUT OFF BEFORE AC OFF, COMMENTS BE INCLUDED IN DATA SHEITS. THIS MISSION AC ON 0121, AC OFF 0822. ASSUMING CORRECT TIME ON, ONE TAPE RAN OUT 0802, OTHER AT 0755.
- 3. REQUEST WIRENS BE CHECKED. WHEN STRONG SIG UP ON S BAND LEFT, AFTER RECEIVER SWITCHED TO RIGHT SAME SIG UP ON A BAND BUT NOT S BAND. WHEN PLANE CLOSE TO SOURCE SIG UP ON S BAND EDTH SIDES BUT CALY ON X BAND LEFT. WHEN SIG CHANGED AFTER TURN, S SAND INDICATED TURN BUT X BAND ON LEFT ONLY.

END OF MESSAGE

25 YEAR RE-REVIEW

F-1-1-1 1Cy only

SECRET

REPRODUCTION OF OTHER THAN THE ISSUING OFFICE S PROHIBITED